
CITY OF BALTIMORE WET SMOKE AND DYED I	Page 1 of 7				
Sewershed: Low Level Subsewershed: 44	Company: REI/DRAYCO	Date: 09/03/2008 Supervisor: E.R. Crew: 04			
Test Type: Smoke	Ground Condition: Dry: X Damp:_ Wet:_				
Manhole ID: S19I046MH	Test ID: 1029-592	Notifications Made:X Residents, Fire, 311			

Field Sketch: (Show all manholes with numbers, blower placement location, sandbag or isolation locations, street names, building addresses and locations, defect locations and photograph numbers)



CITY OF BALTIMORE WET WEATHER CONSENT DECREE SMOKE AND DYED WATER TESTING FORM						Page 2 of 7					
;	Sewershed: Low Level Subsewershed: 44		Company: REI/DRAYCO				Date: 09/03/2008				
Test Type: Smoke			Ground Condition: Dry: X Damp:_ Wet:_				Supervisor: E.R. Crew: 04				
Manhole ID: S19I046MH		T	Test ID: 1029-592				Notifications Made:X_ Residents, Fire, 311				
Field Sketch: (Show all manholes with numbers, blower placement location, sandbag or isolation locations, street names, building addresses and locations, defect locations and photograph numbers)											
Defect		Source			Draina	age	Severity		51		
No.		Type	05	00	Area				Photo Number		
1	30 S. PULASKI ST. 32 S. PULASKI ST.	02	05	02	25		03	_	1029-592_OB01-01.jpg 1029-592_OB02-01.jpg		
3	34 S. PULASKI ST.	02	08 08	02 02	30 15		03 03		1029-592_OB03-01.jpg		
4	38 S. PULASKI ST.	02	08	02	8	,	03		1029-592_OB04-01.jpg		
5	2100 BOYD ST.	02	06	02	4		03		1029-592_OB05-01.jpg		
- 5	2100 BOTD 31.	02	06	01	4		03		1029-392_OB03-01:Jpg		
-											
-											
				 	 						
				1							
				<u> </u>							
		OB	SERVAT		DES						
04 11	Source Type	04 D	Location				ector	64	Severity		
	ain Sewer 10 MH Frame	01 Paved 0					Public	_	No Smoke		
		02 Asphalt					Private	02 Trace			
			Paved Other 12		Golf Course			03 Moderate 04 Major			
		04 Drivewa 05 Sidewal		Other	uise			υ4	iviajui		
		06 Curb	14	Julei	-+						
		06 Cuib 07 Yard - F	ront		-+						
	ound. Drail 17 Tele. Pole	08 Yard - B			$ \vdash$						
	dg. Interio 18 Other	09 Yard - S			$ \vdash$						
				l .					1		

CITY OF BALTIMORE SMOKE TESTING OBSERVATION SUMMARY LOW LEVELSEWERSHED

BALTIMORE CITY PROJECT 1029 REI/DRAYCO

Unique Test ID: 592 Date: 09/03/2008 Basin: LL - 44 Manhole ID: S19I__046MH Defect No: OB01 Supervisor: E.R. Crew: 04 Dye Test Recommended: N

Location: 30 S. PULASKI ST.

Source Type: 02 Service Line Sector: 02 Private

Location: 05 Sidewalk Severity: 03 Moderate Drainage Area: 25

Comments: SMOKE IS COMING FROM ALONG THE SIDE AND IN BACK OF THE HOUSE.

SMOKE TEST PHOTOGRAPHS



Photograph No: OB01-01 Filename: 1029-592_OB01-01.jpg

CITY OF BALTIMORE SMOKE TESTING OBSERVATION SUMMARY LOW LEVELSEWERSHED

BALTIMORE CITY PROJECT 1029 REI/DRAYCO

Unique Test ID: 592 Date: 09/03/2008 Basin: LL - 44 Manhole ID: S19I__046MH Defect No: OB02 Supervisor: E.R. Crew: 04 Dye Test Recommended: N

Location: 32 S. PULASKI ST.

Source Type: 02 Service Line Sector: 02 Private

Location: 08 Yard - Back Severity: 03 Moderate Drainage Area: 30

Comments: SMOKE IS COMING FROM ALONG THE BACK WALL ADJACENT TO ALLEY.

SMOKE TEST PHOTOGRAPHS



Photograph No: OB02-01 Filename: 1029-592_OB02-01.jpg

PAGE 5 of 7

CITY OF BALTIMORE SMOKE TESTING OBSERVATION SUMMARY LOW LEVEL SEWERSHED

BALTIMORE CITY PROJECT 1029 REI/DRAYCO

Unique Test ID: 592 Date: 09/03/2008 Basin: LL - 44 Manhole ID: S19I__046MH Defect No: OB03 Supervisor: E.R. Crew: 04 Dye Test Recommended: N

Location: 34 S. PULASKI ST.

Source Type: 02 Service Line Sector: 02 Private

Location: 08 Yard - Back Severity: 03 Moderate Drainage Area: 15

Comments: SMOKE IS COMING FROM ALONG THE BACK WALL ADJACENT TO ALLEY.

SMOKE TEST PHOTOGRAPHS



Photograph No: OB03-01 Filename: 1029-592_OB03-01.jpg

PAGE 6 of 7

CITY OF BALTIMORE SMOKE TESTING OBSERVATION SUMMARY LOW LEVEL SEWERSHED

BALTIMORE CITY PROJECT 1029 REI/DRAYCO

Unique Test ID: 592 Date: 09/03/2008 Basin: LL - 44 Manhole ID: S19I__046MH Defect No: OB04 Supervisor: E.R. Crew: 04 Dye Test Recommended: N

Location: 38 S. PULASKI ST.

Source Type: 02 Service Line Sector: 02 Private

Location: 08 Yard - Back Severity: 03 Moderate Drainage Area: 8

Comments: SMOKE IS COMING FROM ALONG THE BACK WALL ADJACENT TO FENCE.

SMOKE TEST PHOTOGRAPHS



Photograph No: OB04-01 Filename: 1029-592_OB04-01.jpg

PAGE 7 of 7

CITY OF BALTIMORE SMOKE TESTING OBSERVATION SUMMARY LOW LEVEL SEWERSHED

BALTIMORE CITY PROJECT 1029 REI/DRAYCO

Unique Test ID: 592 Date: 09/03/2008 Basin: LL - 44 Manhole ID: S19I__046MH Defect No: OB05 Supervisor: E.R. Crew: 04 Dye Test Recommended: N

Location: 2100 BOYD ST.

Source Type: 02 Service Line Sector: 01 Public

Location: 06 Curb Severity: 03 Moderate Drainage Area: 4

Comments: SMOKE IS COMING FROM CRACK IN MIDDLE OF THE CURB.

SMOKE TEST PHOTOGRAPHS



Photograph No: OB05-01 Filename: 1029-592_OB05-01.jpg